

**Facilities
NEEDS ASSESSMENT APPLICATION**

Facilities: Programs should list no more than three facility or renovation items. Identify the area in need of physical renovation, maintenance and/or repair. Requests for additional space should also be listed here. *Requests listed in this category will be forwarded to the Facilities Committee to evaluate through their own processes.* Provide a thorough rationale to help the Facilities Committee evaluate your request. List the approximate cost of your request.

Name of Person Submitting Request:	Stacy Meyer
Program or Service Area:	Culinary Arts
Division:	Applied Transportation and Culinary Arts
When was the last Program Efficacy document completed?	2011
What rating was given?	Continue

1. Renovation Request

The hood system in the Sunroom area does not work efficiently. It has not worked correctly since the building was accepted. The situation has been assessed and it has been decided that the unit is too small for the job it has to handle. We need a bigger hood system which will cost around \$ 1 million dollars to retrofit or buy new a hood system to replace the old. In the meantime there is little to no air flow on the line areas. Temperatures can reach upward to 120 + degrees on the hot days, students have to sit down due to the heat and some are getting sick to their stomachs. I am requesting on behalf of the students in the program that the hood system and exhaust system be reviewed again and at least come up with some sort of solution if we can't fix the problem right away.

Approximate Cost: \$300,000.00

2. Renovation Request

Paint for the dining room area in cc169 and cc170- The area is in great need of white paint.

Approximate Cost: I don't think it would run more than \$60.00 the school should have white paint in the warehouse area that can be used for this project.

3. Renovation Request

North Hall kitchen needs some minor repairs in order for classes to be held in this space. The building has been under the schools control for two years now and the repairs have not been completed. The repairs were builder errors however nothing has yet been corrected. The counter tops have to be lifted to 36 inches except for one station that needs to remain at the ADA 32 inches, the trash compactors need to be placed into the holes in the cabinet areas, locks must be placed on all cabinets, the room is full of black widow spiders (we have sprayed multiple times

yet they still return), mice are coming in under the door frames because the doors are not sealed at the floor.

Approximate Cost: I have no idea how much the repairs will be but I would start by calling the builders back in to fix the issues. This should not be a cost to the campus.